

PO BOX 391578  
ANZA, CA 92539-1578 US  
(951) 763-2210  
heritagewellservice@yahoo.com  
www.heritagewellservice.com



# INVOICE

INVOICE # 3605  
DATE 04/20/2015  
DUE DATE 04/30/2015  
TERMS Due on receipt

**BILL TO**  
Mike Pique  
32762 S. Grade Rd.  
Palomar Mountain, CA

**SHIP TO**  
Mike Pique  
32762 S. Grade Rd.  
Palomar Mountain, CA

Please detach top portion and return with your payment.

ACTIVITY	QTY	RATE	AMOUNT
well depth = 440 ft. static = 330 ft.			
<b>Submersibles:Webtrol Submersibles:WT0715</b>	1	740.00	740.00
WT0715 Webtrol 7 GPM 1.5 HP Submersible Pump (includes 5 yr. manufacturer warranty)**			
<b>Submersibles:Sub Motors:Pentek Motors:1.5 HP</b>	1	560.00	560.00
1.5 HP Pentek Submersible Motor 1 PH, 230 V (includes 5 yr. manufacturer warranty)**			
<b>Control Boxes:Pentek Controls:1.5 HP</b>	1	159.00	159.00
Pentek 1.5 HP Control Box (includes 1 yr. manufacturer warranty)**			
<b>Splice</b>	1	35.00	35.00
Splice			
<b>Subcable:#10</b>	425	1.90	807.50
#10 Subcable - 4 wire with a jacket price/ft.			
<b>Galvanized Pipe:1.25' Galvanized Pipe</b>	420	3.50	1,470.00
1 1/4" Galvanized Pipe price per foot			
<b>Valves:1.25' NT Check Valve</b>	1	55.00	55.00
1 1/4" Non Tapped Brass Check Valve			
<b>Misc. fittings:Misc. Parts</b>	1	75.00	75.00
Miscellaneous Parts (safety rope, pipe dope, glue, tape, etc.)			
<b>Well Seals:6' x 1 1/2'</b>	1	95.00	95.00
6" x 1 1/2" Well Seal			
<b>Labor Services:Pump Install</b>	4	100.00	400.00
New Pump Installation with the use of a 6T pump hoist.			

Under the Mechanics Lien Law (CA Code of Civil Procedures, Section 1181 et seq), any contractor who helps improve your property but is not paid for his work or supplies has a right to enforce a claim against your property. This debtor agrees to pay any and all costs including attorney fees which may be necessary in collection of this bill.

ACTIVITY	QTY	RATE	AMOUNT
<b>Labor Services:Misc. Service</b> Miscellaneous Service	1	100.00	100.00
CONDITIONS: THIS ESTIMATE INCLUDES PRICING FOR THE WELL CERTIFICATION WITH A GENERATOR AND A WORST CASE SCENARIO ESTIMATE IF THE PUMP NEEDED TO BE PULLED BECAUSE IT WAS DAMAGED FROM THE FIRE. THIS ESTIMATE DOES NOT INCLUDE ANY REPLACEMENT PARTS THAT MAY BE NEEDED AS THIS INFORMATION IS NOT KNOWN AT THIS TIME.			
<b>Labor Services:Flow Test</b> 2 hour Measured Flow Production Test and Well Certification Report	1	275.00	275.00
<b>Water Samples:Bacti Sample/Flow Test</b> Delivery and testing of water sample for Coliform, E. Coli Bacteria and Nitrates	1	125.00	125.00
<b>Labor Services:Equipment Rental</b> Equipment Rental - use of generator for well test and fuel	1	25.00	25.00
<b>Labor Services:Misc. Service</b> Miscellaneous Service - removal of the well pump at the location if needed	2	100.00	200.00
<b>Comments:Warranty 2</b> **1 yr. warranty on labor, afterwards, customer is responsible for labor fees on any warranty work. Warranty does not include repairs caused by mother nature (ie freezing, sun rot, etc.)	1	0.00	0.00

THE FOLLOWING APPLIES UNLESS OTHERWISE STATED: Any item not specifically mentioned is not included nor intended. Delivery/shipment is estimated and Heritage Well Service is not responsible for delays beyond their reasonable control. This quote is firm for 30 days from above date.

SUBTOTAL	5,121.50
TAX (8%)	319.72
TOTAL	5,441.22
PAYMENT	2,000.00
BALANCE DUE	<b>\$3,441.22</b>